


Hi-Flow Manifold Kits

Part No's - 2226712 & 2226713



These INSTRUCTIONS are for experienced operators. If you are not fully familiar with the principles of operation and safe practices for oxy-fuel gas equipment, we urge you to read our booklet "Precautions and Safe Practices for Gas Welding, Cutting and Heating," Form 2035. Do NOT permit untrained persons to install, operate, or maintain this equipment. Do NOT attempt to install or operate this equipment until you have read and fully understand these Instructions. If you do not fully understand these Instructions, contact your supplier for further information.

The arrangement below is for one torch operation. Use additional pieces of items 17 & 18 to mount this Manifold and inlet fittings are sized for two torches if necessary.



* NOTE: For Torches with "C" Size Cutting Oxy, Use Item 19